



O-RING RECOGNIZER INSTRUCTIONS

Give a quick shake to the tool so that the brass hammer wedges into the upper portion of the tube.



Position the tool upright over the o-ring and gently push the hammer loose with your index finger. Watch closely as the hammer bounces off of the o-ring. The height of the first bounce will determine the material.

